Attorney Docket No. 1664.1001



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

Tetsuo MURAJI, et al.

Application No.: 10/084,945

84,945 ATTENTION

Confirmation No.: 8275 CERTIFICATE OF CORRECTION

Filed: March 1, 2002 BRANCH

U.S. Patent No.: 6,867,582 Batch No.:

Issued: March 15, 2005

For: NON-CONTACT POSITION SENSOR

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450 Certificate AUG 0 5 2005 Of Correction

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: August 2, 2005

Paul I. Kravetz

Registration No. 35,230

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005 Telephone: (202) 434-1500 Facsimile: (202) 434-1501 Approved for use through 09/30/2000. OMD 0651-0033

U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO 1050)

UNITED STATES PATENT AND TRADEMARK OFFICE **CERTIFICATE OF CORRECTION**

PATENT NO: 6,867,582

DATED: March 15, 2005

INVENTOR(S): Tetsuo MURAJI, et al.

Col. 22, line 45, after "wherein" insert --the--.

Col. 23, line 38, change "M0" to -M0a1-.

Col. 24, line 31, delete "each".

MAILING ADDRESS OF SENDER: STAAS & HALSEY LLP 1201 New York Ave., N.W. Suite 700 Washington, DC 20005

PATENT NO. 6,867,582

No. of add'l copies @ 50¢ per page